Government College of Engineering and Research, Avasari(Khurd)

Department: Mechanical Engineering

Learning Resource Material (LRM)

Name of the course: Mechanical System Design Course Code: 402048

Name of the faculty: J. M. Arackal Class: BE(Mech)

SYLLABUS (Unit 1)

Unit 1: Design of Machine Tool Gearbox (8 Hours)

Introduction to machine tool gearboxes, design and its applications, basic considerations in design of drives, determination of variable speed range, graphical representation of speed and structure diagram, ray diagram, selection of optimum ray diagram, deviation diagram, difference between numbers of teeth of successive gears in a change gear box.

Lecture Plan format:

Name of the course: Mechanical System Design Course Code 402048

Name of the faculty: J. M. Arackal Class: BE(Mech)

Unit No	Lecture No.	Topics to be covered	Text/Reference Book/ Web Reference
		UNIT 1	
1	1	Introduction to machine tool gearboxes, design and its applications	1,2
1	2	Basic considerations in design of drives, determination of variable speed range	1,2
1	3	Graphical representation of speed and structure diagram, ray diagram	1,2
1	4	Problems on Formation of Structural Equation	1,2
1	5	Problems on Speed Diagram	1,2
1	6	Problems on Ray Diagram	1,2
1	7	Problems on Design Layout of gearing mechanism for a particular speed range	1,2
1	8	Problems on Design Layout of gearing mechanism for a particular speed range	1,2

List of Text Books / Reference Books / Web Reference

1-Bhandari V.B. —Design of Machine Elements, Tata McGraw Hill Pub. Co. Ltd.

2-R.K. Jain- Machine Design, Khanna Publishers

3-Johnson R.C., —Mechanical Design Synthesis with Optimization Applications^{||}, Von Nostrand Reynold Pub

```
Design of Speed Box
   used for stepped regulation of rpm.
     Between two extreme available values n. & nz
      what should be conteria for choosing descrete.
      steps [. let z be no of steps ]
& Laws of speed range distribution
Sa) RPM values constitute Anithmetic progression
        n_2 = n_1 + a = n + q
         n_3 = n_2 + a = n_1 + 2q
        -- (n2 = n,+(z-1) a
             ⇒ d = 1000 V
    .. upper limit of dia
               dx = 1000 V
      Lower limit of clia.
              dx+1 = 1000 U
         -- Ddr = 1000 V [ 1 - 1 mx+1
                                          V= 20 m/mix
                  n_2 = 375 z = 12
     lut n = 30
                                       Ddx .
                              dx
                    ф
                                       08-47
      nx 91pm.
                             2/2.18
                   2.04.
                                       35.1
    n_i = 304
                             103.7.
                   1.5%.
                                       17.3
    n2 = 61.4
                             68.6
                                       10-34.
                   1.33.
    ns = 92.8
                              51.25
                                       6.87
                  1.25
                              40.91
    n4 = 124.2
                                        4-89.
                   1.21
    ns = 155.6
                              34.04
                   1.17.
                                        3.67
                              29.15
    n 6 = 187
                   1.14.
                                        2.84.
     m= 218.4
                              25.48
                   1.13.
                                        2.28 .
     ng = 2498
                              22-64.
     ng = 281.2
                   1.11
                                        1.84.
                              20.36
     nio= 312.6
                   1.10
                                         1.53
                              18.50
     n 11 = 344
                   1.09 .
                               16.97.
     MIL - 375
```

Baciala	. ,	4 44			~ 1
-Bosinlar +	he ahava	inge some	1	e hood	exilo
- At high	Sipm Ito	inge some	values of	Special	The state of
Iredund	ant.	A SOPPON	1 4	oh bet	wem x
- Low ra	nge no	ed to add	more s'	95	3 1/
Calcu	lated with	ed to add us.	. A	Prom	mal (ican I)
L) RPM Va	lues co	nstitute G7	Geo mil	ue d'og	Just (VV)
$\mu' = \lambda$			TIN ISA	we tidan	1-100
	in,		i didano.	v= tram	11 7
n3 = (172= 44	11 - 6 17,		. Or = 15	1000 820
n 2	= q2-1n;		1/10	0+10 = a	
ф <u>-</u>	$\left(\frac{n_2}{n_1}\right)^{\frac{1}{2}}$	= 1.26.		0+ 20 0 EM	
	- 7/1			= = 17/	
noc	ф	dx 2121		Dd21	
n ₁ = 30	1-26	168.4		43.78	
n2= 37-8	1.26	133.6		27.58	
n3= 47.63.	1-21			2).88.	
74= 60.014	1-26	1 66.0		7.38	7
ns= 75.62.	1.26	84.18	7/	- 67	
no= 95.3.	1.26	66.8	11	الوا	1
$n_1 = 120$	1.26	53.04	0	68	á.
	1.26	4 2.09	7		
ng= 151.2.		33.4	, — 6	29.	
ng = 190-51	1.26	265	V 5.4	47.	
nio= 240 ·	1.26 -	2/.03		s.	
$n_{11} = 302.4$	1.26	16.9	40.1		
h12 = 314 375	1.21.	1 1 1 2 1 - 8 - 1			
		II AP			

effective than AP

metric progression is commonly used in machine tool 1) Constant loss of economic cutting. Speed.
Suppose spinde opm constitute the following series n, n2 n3 -Let Vopt like between ny & my+1 i. we have. Itdny _ Vopt < Tidny+1 The difference between the actual cutting Speed & the optimum cutting speed is known as. the loss of economic cutting speed.

Loss is maximum when the optimum cutting.

Speed lies in the middle of two speeds. Vop+ = tid (nj+ nj+1) - (\(\nu_{\psi} \) max = \frac{\pi d}{1000} \left(\frac{n_{3+1} - n_1}{2} \right). from the above we have. (AV) max = (ny+1 + ny) Vopt. Denoting $\frac{n_{j+1}}{n_j} = \phi_j$ we have. (A V+) max = (\$1-1) Vont So of (D 1/4 Image is to remain constant. dy should be constant. ie it should be in GP.

Manager and the second

If the sipm values are obtained by mounting new parts of gears on the shaft everytime, then 2) Better Design flalare; changing of speeds becomes time-consuming. If the Irpm values are obtained by mounting glass. inconvinient & infeasible, of appropriate transmission ratio on the shaft permanently, then axial climensions of Buch a Speed. box becomes too large. So it concludes that speed steps in a speed box should be obtained not through q. single transmission between two shafts but, through group of transmissions between number of shafts. this is possible 4 it is in G-P(4) i) If members are so semoved that only every It member remains, then the resulting Series. into having Progression ratio & ii) 4 ¢ is multiplied by a constant A, the resulting series is a GP having same progression ratio but whose members are Atimes greater but whose members are Atimes greater iii). If a is multiplied by of the resulting series is a GP. which is shifted by x members. 30 J constant loss of productivity in whole upm rang MRtal removed in unit time = TId n.S = 1000SV. S-> feed, mm/sev for a sconstant value of, feed s & depth of cuty the productivity of a machining operation is constant in the whole rpm range.

al information required for designing peed Box: Selection of Range radio The following information is required.

i) The highest output, nmax.

2) The lowest output, nnon.

3) The number of steps Z into which the range.

i's divided.

1-111- and number of 4) no of stages in which the negd number of steps are to be achieved Range Ratro, Rn = Mmax - Vmax dmax - Ro Rd. Vmin dmin fixing of higher speed limit involved productives iloss in some machining operation. A wiele range is not practicable. Ru should be kept within Range of diameter should also be selected.

on the basis of statistical study of the working.

of similar machine tools. reasonable limit. Rn = nmax - p2-9= (Ro) 1/2-1. Z- log p = 1 log Rn. Z-1 - log &n = log . Rn + log \$ $Z = \frac{\log R_n + 1}{\log 4}$ Z = log kn + log d. mulliples of 2 &3. Z= rounded off in

Roserier - 5/10 = 1.58 Rio Senies - 10) 10. = 1.26 = 1.12. R20 Serles - 10 = 1.06. Ruo seria - \$ 10 = 1.03. R80 sester - 89 10 Structural Diagrams & their Analysis to Solid Best possible version. Suppose a speed on one shoft yield two. Speed values on the next shaft, is no of speed, stens of the particular transmission group is. P=2: the two new speed should be in. the following stange.

Limin = 1/4. The transmission range for the group ig = lmax = 8 n2 on 9. Suppose there are Z 8 tels n, n2 -. Particular transmission group such that $\frac{n_1}{n_1} = \frac{n_2}{n_2} = \frac{n_2}{n_2-1} = \frac{1}{n_2-1}$ K= px. xis known as characteristic of the. transmission group. I denotes the no. of steps of. the spindle rpm geometaire progression by which two adjacent opm value of the. pastículas group are seperated. The Lansmission grange of mth group. can be calculated Cm = p C.Pm - U Xm. for obtaining particular number of speed steps using min. no of gears its necessary that R1=P2 --- = pv // p= z'v.

```
ne number of speed steho is represented by.
                     Z=P1 x P2 x ... Py.

Massi elaborate expression.

| p= no of specistum.
                      More elaborate expression.
                       Zu=P(x) P2(x) P3(x3).. Po(x0).
                                 where x,=1 X2=P1 X3=P1P2-
Eg: Let no of speed 5 teps z= 12. & Let 1+
                       be realized in 3 stages v=3 and multiplicated the number 12 can be written as multiplicated
                of 2£3 in 6 different ways, one such.

Combination. p_1 p_2 p_3.

p_3 p_4 p_5.


p_4 p_5.

p_6 p_6.

p_6 p_6.

p_6 p_6.
ar we can have six structural formula.
                                                                                                               \Rightarrow \frac{7}{x} = \frac{P_1(x_1)}{x} \frac{P_2(x_2)}{P_2(x_1)} \frac{P_2(x_2)}{P_2(x_2)} \frac{P_2(x_2)}{P_2
                                                                                                                                      X,=1 *= P== 2 ×3=, P, P2:
                                                                                \frac{\chi_{1}}{Z} = \frac{\chi_{2}}{2} = \frac{\chi_{3}}{2} = \frac{6}{6}.
\frac{\chi_{1}}{Z} = \frac{2(1)}{3(2)} = \frac{2(6)}{3(2)} = \frac{3(6)}{3(2)} = \frac{3(6)}{3
              a) · P.
                          P2 12 x3.P3.
                                                                                                                2(1) -> shaft 2, has 2 gears & each gi'eld
                                                                                                             3(2) -> Shaft3 how 3 geon I eachyiely
                                                                                                            2(6). -> Shaft 4 has 2 gears & each yields.
              1)
                                                                                                                                                                                          6 s peed rays
                                                                                                                                           2= P.(X3) P2(X1) P3(XL).
                                                                                                                                                   where X = 1, X= P=3, X= P2P3=6.
                b) · 6 ×3 ~ -
                                      P2 × >> ×2 P3.
                                                                                                                              2=2(6)3(1) 2(3.)
                                                                                                                                    Z = P_1(x_2) P_2(x_3) P_3(x_1).
                                                                                                                                  X1=1 X2=13=2 X3=P1B=4.
               c). P.
                                                                                                                               Z = 2(2) 3(4) 2(1)
                              P2×3. 1 P3-
```

```
2 =2×3×2.
Z = P_1(Y_L) P_2(X_1) P_3(X_3)
P2X1 33 P3. X1=1 X2= P2 X3= P1 P2.
            X1=1 X2=3 x5= 6
       Z = 2(3) 3(1) 2(6)
2). P. (xi) P. (xi) B (x2).
P_{2}(x_{3}, (x_{3})P_{3}) = X_{1} = 1 \quad x_{2} = P_{1} = 2, \quad x_{3} = 4 = (P_{1}B_{1})
\boxed{2(1)} \quad 3(4) \quad 2(2.).
       Z=P((x3) B(x2) B(x1).
 PL(XL) (X, P3. X=1 XL=P3 X3=P2P3.
            K1=1 K1=2 K3=6.
       2=2(6) 3(2) 2(1)
  .. The Six storuttural formulae are
 1) 2 = 2(1) 3(2) 2(6)
2) 2 = 2(6)3(1)2(3)
3) 2 = 2(2)3(4)2(1)-
4) Z = 2(3)3(1)2(6).
 5). 2 = 2(1) 3(4) 2(2).
 6) Z = 2(6)3(2)2(1).
            XI= 1 [Main transmission group]
```



The selection of the best version is guided, following two factory.

A) Transmission 919tio 27est richion

B) Minimum total shaft size.
If 91pm for GP then torque also will be in GP.

we have P= 277 M KW.

 $M_{+} = \frac{160 \times 10^{3}}{271} \frac{p}{m}.$

 $M_{+} = \frac{kP}{n}$

we have $\frac{M+}{J} = \frac{7}{9}$.

 $M_{+} = \frac{T}{n} \times J = \frac{T \times 2}{d} \times \frac{I}{32} d^{4} = \frac{\tau \pi}{14} d^{3}.$

 $M_{L} = 0.2 d^{3} - 2$

from 0 20-

0.2d2= kp

 $\int_{\mathbb{R}^{n}} d^{n} = \left(\frac{k}{0.2 \, T} \frac{p}{n}\right)^{n}$

 $-i-d_1 = \left[\frac{k}{0.2T} \frac{p}{n_1}\right]^{\frac{1}{3}} d_2 = \left[\frac{k}{0.2T} \frac{p}{n_2}\right]^{\frac{1}{3}}.$

 $-\frac{1}{d_2} = \frac{1}{2} \left(\frac{n_2}{n_1}\right)^{\frac{1}{3}} = \phi^{\frac{1}{3}}.$

The best version which ensures.

De d= men.